

Maintenance of Resin Floors

Data Sheet Ref:
CLNG/11/03

Page 1 of 2

Recommendations for Cleaning

Having invested in a high quality flooring system, such as a resin coating or screed, it is essential that a regular cleaning regime is adopted. This will not only enhance the appearance and life of the floor finish by removing dirt and contamination, but will also ensure that floors are kept safe and hygienic and free from slip hazards.

Resin Surfaces Limited has a range of maintenance cleaning products specifically for resin floor finishes. Formulated using natural derived and ecologically sound materials, the range of products contains no caustic alkalis, harmful solvents, phosphates, silicates or aggressive biocides. They are safe in use and have a superior environmental profile.

FREQUENCY

Cleaning should be carried out on a regular basis; frequency will largely depend on the type of contamination and level of cleanliness required. For maximum effectiveness, cleaning should be carried out on a daily or weekly basis as part of standard housekeeping procedures.

THE PRODUCT

RS INDUSTRIAL FLOOR CLEANER



Titan Hose, Lowick Close
Newby Road Industrial Estate
Hazel Grove, Stockport
Cheshire SK7 5ED, England

A versatile aqueous industrial floor cleaner and degreaser. Its powerful cleaning action effortlessly removes most types of soiling including greases, grime, oils and hydrocarbons. RS Industrial Floor Cleaner leaves no smears or residues upon rinsing. Suitable for use with manual systems with cold or warm water, or with floor scrubber/dryer machines.

Dilution Rate: 1:20 to 1:50.

Estimated Coverage: 50m² to 250m²
(per litre product supplied)

Tel: 0161 483 1232

Fax: 0161 483 2565

MAINTENANCE CLEANING

This system is designed for regular maintenance cleaning as part of standard housekeeping procedures.

PREPARATION

1. Where possible, move portable equipment/machinery to one side to leave a clear unobstructed floor area.
2. Sweep floor to remove loose material and surface debris.

MAINTENANCE CLEANING

1. To a combination floor scrubber/dryer machine, attach red pads or stiff nylon brushes and carefully add a 2% solution (1:50) of **RS Industrial Floor Cleaner** to the machine tank.
2. Use the floor scrubber/dryer machine and simultaneously scrub the floor and wet vacuum the soiled water into the recovery tank.
3. For heavily soiled floors make the first pass of the machine without using the vacuum facility, this leaves the product in contact with the dirt longer and aids removal. On the second pass, scrub the floor and recover soiling as normal.
4. Depending on the floor area, it may be necessary to change the red pad during this operation.
5. Alternatively, dilute **RS Industrial Floor Cleaner** or at a rate of 1 part product with 20 to 50 parts warm water in a mop bucket.
6. Apply solution generously to small sections of the floor with the mop used in a figure of eight motion, repeat until floor area has been completely covered.
7. Rinse thoroughly with clean warm water.

OTHER PRODUCTS

Resin Surfaces Limited has an extensive range of products for maintenance of resin flooring. :-

RS Oil Remover

RS Tyre Mark Remover

RS HD Tyre Mark Remover

RS PVC Tape Remover

RS Fats & Grease Remover

RS Chewing Gum Remover

RS Machine Cleaner

RS Tool Cleaner

For further details please contact our Sales Department.